

Supry, Fred L.

To: archkoontz@aol.com
Subject: Model 700 serial #: G6218322

Dear Arch:

We checked the rifle that you returned and were unable to duplicate the concern. We did notice that the top of the sear was caked with a dark substance. It did not appear to be graphite, but could have interfered with the sear holding the firing pin. We are going to clean the action, install a new trigger assembly, and test the rifle before returning it to you. This will be done under warranty.

Fred Supry
Consumer Affairs Specialist
AFTE Technical Advisor
Law Enforcement Training Instructor
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Office: 315-895-3606
Fax: 315-895-3661

fred.supry@remington.com