

Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: M700BDL .243	Serial Number: 6540941	
Name: Bruce J. Mouat	Date of Purchase: 1971-?	
Address (no PO Boxes): Sgt. Bruce J Mouat C/O Abington Twp. Police 1166 Old York Road		
City: Abington	State: Pa.	Zip: 19001
Phone (Daytime): 215-576-6503	Fax: 215-886-1455	
E-mail Address: BJMouat@Yahoo.com Wk. 215-536-1100 215-885-4450		
Please describe your problem: Safety Modification Program		
Safety and bolt repair as per recall and bolt lock modification		
Additional Information: (Ammo type, brand, handload specifications, etc.)		
NOTE This rifle has discharged after pushing the safety off.		
Please check the SAFETY on this rifle.		
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.		
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p> :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. </p>		

could not duplicate concern.
 Trg. set screws altered, +
 Trg. works sluggish/sticky.
 Room a dried lubrication residue.
 Replace TPA clean & check over for
 cost of safety mod. program of \$20.00
<http://www.remington.com/support/repairsvc/repairform>

Serial
Number:

6540941

Model: 700



RE00092217