

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL
LCS

CUSTOMER ORDER NO.
87563

DATE RECEIVED 01/29/91 DATE OPENED 02/05/91 DATE CODE EE 10-84 SERIAL NUMBER B6639409 MODEL AND GRADE 700 30-06 BDL ORDER R 91-03643

ACCESSORIES W/STUDS

FROM:

AHLMAN'S
ROUTE 1 BOX 20
MORRISTOWN

MN 55052

SHIP TO:

AHLMAN'S
ROUTE 1 BOX 20
MORRISTOWN

MN 55052

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☒ MARRED

CUSTOMER'S REQUEST

I red when closing bolt safety sticks

for evaluation

Sent to J. Stokl

MAIN FAULT

No fault found - cannot duplicate complaint

Tugger guard safety assembly operating properly Tugger pull 5 1/2 #; sent left 015"

PARTS

butt of stock marred several places, trigger guard scratched

offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

TO: Roxington # 87563

This firearm has the following defect: fired when
closing bolt
safety sticks

Please repair under warranty at no charge and return directly to us.
If not covered by warranty, please send repair estimate before
proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Merristown, MN 55052