

Don Akers
21562 140th Ave
Tustin, Mi. 49688
1-231-775-4320

Call Don
231
884 0490

Remington
14 Hoefler Ave
Ilion, NY 13357

Attention: Fred Supry

Sir: per my phone conversation with Dennis, I am shipping my rifle back for your inspection and repair. The incidents that occurred were as follows.
This past Saturday after firing at a deer, the weapon fired when I chambered a fresh cartridge. I thought it was a fluke. Tuesday evening I fired at another deer and when I chambered fresh, I could not squeeze a round off, the trigger was solid, with no pull. I checked the safety and the bolt alignment and both were in the proper position. Each time I rechambered a fresh cartridge I had the same result, could not move the trigger. I then ejected the cartridge, removed the clip and hand fed a new cartridge into the chamber. The rifle was in my lap as I was close inspecting it. When I closed the bolt and seated it locked, it discharged through the wall of my hard side enclosed deer blind. I didn't mind the damage there, but the concussion has left me, at this writing, with ringing ears, headache and equilibrium problem.

I hope you can solve this mechanical problem for me, it is a scary feeling. I have hunted deer since 1954 and have never had this experience.

Thank you,

Don Akers

Don Akers

P.S This rifle is a sweet one to use. I have killed a lot of bucks with it and find it extremely fast and accurate. I was totally surprised by this problem.

Herb,

*Clean, check over completely,
new Ejector spring if needed,*

n/c

- Loose TA - tightened & sealed

Charge 230145

FCS 12/12/01

Serial
Number:

A6096295

Model: **788**



RE00036701