

Repair Order Number



|                                                                                          |                                              |                                                                                           |
|------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------------------------------------------------------|
| <b>Repair Order Number</b><br>RE00061250                                                 | <b>Description/Serial Number</b><br>E6733761 | <b>Repairman -</b> Chuck Dekanek                                                          |
| <b>Account # - R-</b>                                                                    | <b>Model 700 Center Fire Caliber: 7 MM08</b> | <b>Date Received -</b> 2/10/2003                                                          |
|                                                                                          | <b>BDL</b>                                   | <b>Estimate Date -</b>                                                                    |
|                                                                                          |                                              | <b>Current Date -</b> 2/18/2003                                                           |
| <b>Customer</b><br>AMERICAN SPORTSMAN<br>4088 WASHINGTON RD<br><br>MARTINEZ. GA 30907 US |                                              | <b>Return To</b><br>AMERICAN SPORTSMAN<br>4088 WASHINGTON RD<br><br>MARTINEZ. GA 30907 US |
| <b>Phone (H)</b> (706)-863-4868                                                          | <b>Fax</b>                                   |                                                                                           |
| <b>Phone (W)</b>                                                                         | <b>Email</b>                                 |                                                                                           |

| Reported |                                           | Problems Found |                              |
|----------|-------------------------------------------|----------------|------------------------------|
| M123     | FORWARD TO PRODUCT SERVICE FOR INSPECTION | M123           | FORWARD TO PRODUCT SERVICE F |

| Repair                |                               |                            |                              |                              |                           |
|-----------------------|-------------------------------|----------------------------|------------------------------|------------------------------|---------------------------|
| <u>Material #</u>     | <u>MaterialDesc</u>           | <u>Quantity<br/>Needed</u> | <u>Quantity<br/>From Inv</u> | <u>Quantity<br/>From Kit</u> | <u>Warranty<br/>(Y/N)</u> |
| <b>Part</b>           |                               |                            |                              |                              |                           |
| F26345                | 700 TRIG ASSB RH              | 1                          | 1                            | 0                            | Y                         |
| <b>Part Total:</b>    |                               | 1                          | 1                            | 0                            |                           |
| <b>Service</b>        |                               |                            |                              |                              |                           |
| 4000294               | GR-CHECK TPA                  | 1                          | 1                            | 0                            | Y                         |
| 4000104               | ARMS SERV SHIPPING & HANDLING | 0                          | 0                            | 0                            | Y                         |
| 4000119               | GR-TEST                       | 1                          | 1                            | 0                            | Y                         |
| <b>Service Total:</b> |                               | 2                          | 2                            | 0                            |                           |

|                       |                                                                                                                                                                                      |              |             |               |                |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------|---------------|----------------|
| <b>ProblemNotes</b>   | Rust found at trigger pin hole and on trigger.Small metal chip found inside the housing.Rust at trigger pin could have seized trigger.Replace trigger assembly at no charge per DJS. |              |             |               |                |
| <b>Repairman</b>      | <b>Proof</b>                                                                                                                                                                         | <b>Clean</b> | <b>Test</b> | <b>Target</b> | <b>Pattern</b> |
| <b>Gallery Tester</b> | <b>Date</b>                                                                                                                                                                          | <b>Date</b>  | <b>Date</b> | <b>Date</b>   | <b>Date</b>    |