

Serial
Number:

T6239713

Model: 700—



RE00075737

1/16/04

Could not duplicate the customer
reported concern

The action was found faulty & several
tugger assem comp was made
Poor maintenance

Clean action & replace tug assem
1/2 MSP Quote