

Repair Order Number



Repair Order Number

RE00050540

Description/Serial Number

B6786815

Repairman - Robert Frink

Date Received - 8/14/2002

Account # - R-

Model 700 Center Fire Caliber: 30 06

Estimate Date -

ADL

Current Date - 8/20/2002

Customer

BRUCE ANDERSON  
110 GENERAL KNOX RD

Return To

BRUCE ANDERSON  
110 GENERAL KNOX RD

RUSSELL, MA 01071 US

RUSSELL, MA 01071 US

Phone (H) (413)-568-7391

Fax

Phone (W)

Email

### Problems

Reported

M123 FORWARD TO PRODUCT SERVICE  
FOR INSPECTION

Found

M123 FORWARD TO PRODUCT SERVICE F

### Repair

| Material #            | MaterialDesc                  | Quantity<br>Needed | Quantity<br>From Inv | Quantity<br>From Kit | Warranty<br>(Y/N) |
|-----------------------|-------------------------------|--------------------|----------------------|----------------------|-------------------|
| <b>Part</b>           |                               |                    |                      |                      |                   |
| F26345                | 700 TRIG ASSB RH              | 1                  | 1                    | 0                    | Y                 |
| <b>Part Total:</b>    |                               | 1                  | 1                    | 0                    |                   |
| <b>Service</b>        |                               |                    |                      |                      |                   |
| 4000104               | ARMS SERV SHIPPING & HANDLING | 0                  | 0                    | 0                    | Y                 |
| 4000116               | GR-LABOR                      | 20                 | 20                   | 0                    | N                 |
| 4000118               | GR-CLEAN                      | 1                  | 1                    | 0                    | Y                 |
| 4000119               | GR-TEST                       | 1                  | 1                    | 0                    | Y                 |
| <b>Service Total:</b> |                               | 22                 | 22                   | 0                    |                   |

ProblemNotes

Concern - Gun will fire when safety is pushed off. Fault Found - Could not duplicate concern. Altered adjustments and sticky residue. Install new trigger assembly and clean action. Charge \$20.00. FLS 8/13/02.

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| Repairman      | Proof | Clean | Test | Target | Pattern |
| Gallery Tester | Date  | Date  | Date | Date   | Date    |

REXINGTON ARMS CO INC  
800 243-9700  
14 HDEFLER AVE  
ILION NY 13357


10 LBS 1 OF 1

**COD**

**SHIP**

**TO:**

BRUCE ANDERSON  
110 GENERAL KNOX RD  
RUSSELL MA 01071




**MA 011 9-04**



**UPS GROUND**

TRACKING #: 1Z 114 813 72 1192 8023



BILLING: P/P  
COD \$20.00

INV#: RE00050540

ASC 05.00 J69X/J64X 16.0A 01/2002