

Date: 11/09/04
By: Bruce W. Hanks

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Billy J. Clark
R.E. Number: 87636
Reason for inspection: fire on bolt closing

FIREARM

Manufacturer: Rem. Model: 700
Serial Number: 6683546 Date of Manufacture: 10/73
Overall external condition: Good

Barrel condition: okay

Receiver condition: okay

Stock condition: okay

Bolt/firing pin condition: okay

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: parts work sluggish

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 7.5th

Manual safety: okay bolt lock

Test firing results (if applicable): _____

DISPOSITION

could not duplicate
trig assm. is dirty and has a sticky residue
on it causing parts to work sluggish! replace
TPA + clean action under bolt lock program for
ADDITIONAL COMMENTS \$20.00 go ahead