

Remington®

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: A6814044	
Name: Jackey R. ANTHONY	Date of Purchase: 1978	
Address (no PO Boxes)::		
3506 Vantage Lane		
City: Amarillo	State: TX	Zip: 79109
Phone (Daytime): 806.376.6273	Fax: 806.349.5199	
E-mail Address: janthony@brucknermack.com		
Please describe your problem: Bought this gun brand new in 1978. When you take it off of safety, it has fired several times. This gun has never been taken apart & has had 50-60 rounds shot.		
Discovered that there was a factory defect causing this problem.		
Additional Information: (Ammo type, brand, handload specifications, etc.)		
Remington 30-06 Springfield		
150 gram Core-Lokt Pointed Soft Pt.		
R30062		
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.		
<p>ⓈWARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it.</p> <p>:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>:: Remove all accessories from your firearm to prevent loss or damage.</p> <p>:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>		

Jackey R. ANTHONY
OV 7/19

33414

Remington Arms Co Inc
14 Hoefler Ave
Ilion NY. 13357