

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00066953 Account # - R-	Description/Serial Number E6442432 Model 700 Center Fire Caliber: 22250 BDL / WITH SCOPE	Date Received - 6/26/2003 Estimate Date - Current Date - 7/1/2003
Customer ANTIOUE AND MODERN FIREARMS INC 2263 NICHOLASVILLE RD LEXINGTON, KY 40503 US	Return To ANTIOUE AND MODERN FIREARMS I 2263 NICHOLASVILLE RD LEXINGTON, KY 40503 US	
Phone (H) (859)-276-1419 Phone (W)	Fax (859)-278-0838 Email	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO		
M992	FIRE WHEN BOLT WAS CLOSED				

Technician's Comments	
Condition	MARR ON LEFT SIDE OF STOCK BY TRIGGER
Problem/Notes	Action and trigger assembly dirty. Small metal machining chip found inside the housing. Clean action and replace trigger assembly complete at no charge. D.S.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service Total:		2	