

Remington®

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: A6733899
Name: DON ATKINSON	Date of Purchase: ?
Address (no PO Boxes): 101 BEATY LANE #121	
City: ALLARDT	State: TN Zip: 38504
Phone (Daytime): 931-879-5023	Fax: 931-879-0794
E-mail Address: M3333@INFOAVE.NET	
Please describe your problem: GUN DISCHARGED WHILE WORKING BOLT TO UNLOAD. ALSO INCLUDING CHECK FOR "20" FOR SAFETY MODIFICATION FOR REM PRE-1982 RIFLES. PRODUCT SERVICE REPRESENTATIVE SUGGESTED SENDING RIFLE TO YOU FOR INSPECTION OF CAUSE OF FIRING WHILE	
Additional Information: (Ammo type, brand, handload specifications, etc.)	
BOLT WAS BEING WORKED.	

49476

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

⚠ **WARNING:** DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- ⚙ Record the serial number of your firearm before sending it.
- 📦 Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- 🧰 Remove all accessories from your firearm to prevent loss or damage.
- 📦 Ship your **INSURED** firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Serial Number: **A6733899**

Model: **700**



RE00049476

Altered adjustments & gummy, sticky residue.
Sent in for bolt lock modification
Clean action, install new TA.
go ahead
FLS 7/24/02

5/20/02 9:26 PM

PS00826