

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-12988

INITIAL CUSTOMER ORDER NO.

ATTN: DENNIS SANITA

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/13/94

04/14/94

DS 7-69

6255392

700 30-06

ADL

ACCESSORIES

L/SIGHTS

L/STUDS

FROM:

BROWN, RAY
101 SUNSET
HEWITT

TX 76643

SHIP TO:

BROWN, RAY
101 SUNSET
HEWITTTX
76643

CUST NO: 095911 GLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER NO.

059015

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRIED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

C1

D1

E1

F1

TRIGGER GROUP

B2

C2

D2

E2

F2

BOLT ASSY.

B3

C3

D3

E3

F3

BARREL ASSY.

B4

C4

D4

E4

F4

REC. ASSY.

B5

C5

D5

E5

F5

WOOD

C1

C2

D3

E5

F5

METAL

C2

C2

D3

E5

F5

MAIN FAULT

We could not duplicate customer concern, however, I suspect
would that there is a fault in the trigger assembly.
I suspect this has been removed from your equipment, indicating it has been
300 yds. 004 target with. Called customer, he stated he didn't split in
500 yds 4:15 to 4:30 and has never target with off. again.

Replace trigger assembly request

Truly is a great job of good work, I agree
to replace customer trigger assembly & clean
the action. I explained to Mr. Brown what we
would have a service charge for the labor
involved.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/84