

CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-07695

CUSTOMER ORDER NO.

ATTN: ROGER POTTER

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
1/93	03/18/93	KU 5-71	6425422		700 25-06	BDL
SERIES	W7STUDS					

SHIP TO:

BROWNE, JAMES F. JR.
1401 PATRICIA #212
SAN ANTONIO

TX 78213

BROWNE, JAMES F. JR.
1401 PATRICIA #212
SAN ANTONIOTX
78213

CUST NO: 076750 C.O.D

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
CONDITION					REPAIR CHARGE
W					EXCISE
SLIGHTLY WORN					TAX
DRN					INSURANCE
RY WORN					UPS
IREPAIRABLE					PARCEL POST
RRRED					TOTAL

COMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
IER GROUP		B2			E1	F1
ASSY.		B3			E2	F2
EL ASSY.		B4		D1	E3	F3
ASSY.				D2	E4	F4
			C1	D3	E5	F5
			C2			

AULT

Upon receipt of the inspection. Trigger will not engage, firing
pin follows down when closing bolt. Examination revealed
that all three (3) adjustment screws have been adjusted

outside the factory. Trigger mechanism removed. Top screw had not
been fully 1971

Trigger pull 3 lbs
Sensitivity .007

Replace complete trigger assembly
at 1/2 normal replacement cost
to factory of go will
go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6825 REV. 1/92

PS00910