

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER

R 93-13398

INITIAL FPS	CUSTOMER ORDER NO.					
DATE RECEIVED 06/09/93	DATE OPENED 06/10/93	DATE CODE RR 11-68	SERIAL NUMBER 379389	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN BDL	
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS		

FROM:	SHIP TO:
<i>Setup full</i> BRAUN, FRED SPORTING GOODS 405 OVERLAND STREET KENAI AK 99611	BRAUN, FRED SPORTING GOODS 405 OVERLAND STREET KENAI AK 99611

CUST NO: 079973 C.O.D L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

GUN CONDITION	REPAIR CHARGE
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED	2300 EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD				D3	E5	F5
METAL			C2			

MAIN FAULT: Rifle mfg 1968 upon receipt rifle does not cock, firing pin follows down. Examination revealed that the trigger adjustment and stop screw have been altered without authority. Also found trigger pin rusty.

PARTS	COMMENTS
	Replace trigger assembly completely and clean action at 1/2 normal adjustment cost at discretion of govt. will go ahead.
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTE	DATE

OFFICE COPY

RD6925 REV. 1

PS00915