

Tony Bonura
3112 Kansas Avenue
Kenner, Louisiana 70065
Phone: (504)443-5674

March 13, 1993

Remington Arms
Service Division
14 Hoesler Avenue
Ilion, New York 13357

Dear Sir:

I would like to have the enclosed Remington Model 700-LH serviced. On several occasions, after the rifle has stood in the gun cabinet for a few days or longer, when I first bolted the rifle the firing pin did not cock (the button on the rear of the bolt is in the forward position and the gun will not fire). Also, on one occasion after the gun had sat up for several months, ~~the firing pin did not cock and the bolt~~

I spoke with a gentleman by the name of Dennis (at 315-895-7493) who said if I sent the rifle in you would try to repeat the problem, and if you were unable, you would change the firing system in the gun for half price.

Please feel free to contact me for any information at 504-736-6586 or 504-443-4674.

Sincerely,


Tony Bonura