

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)FDATE (I)NQ (E)XACT 04/05/93
ENTER REPAIR NUMBER -----> 9223376 09 17 32
SERIAL NO: B6277549 NEW SERIAL NO: MODEL: 700
FROM: (CUST NUM: 008349) BOBSARMYNA GA/CAL: 7MM MAG
BOBS ARMY & NAVY TYPE: ADL
C/O NBS ACCESSORIES: W/STUDS
229 E MARKET ST.
CLEARFIELD PA 16830
SHIPPED TO:

DATE CODES: BB 1-81
OTHER ACCESSORIES:
L/REAR SIGHT

COMMENTS:

DATES:		TO	FROM	
RECEIVED	10 29 92	GALLERY 00 00 00	00 00 00	ENTERED BY: FPS
OPENED	11 04 92	PROD SERV 11 17 92	11 18 92	REPAIRMAN: HB
ESTIMATED	11 19 92	TAG GUNS 00 00		TYPIST:
PROMISED	00 00 00	REJECTED 00 00		CORRESPONDENT:
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: W
SHIPPED	01 29 93			

BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9223376 REPR NOT AUTHORIZED WILM INVOICE PR 04/05/93
CUSTOMER NAME: BOBS ARMY & NAVY 09 17 45

REQUEST: "GUN DISCHARGES ON OCCASION WHEN COCKING WEAPON"
MAIN FAULT: NO FAULT FOUND - CANNOT DUPLICATE ABOVE COMPLAINT & CANNOT
MAKE RIFLE MALFUNCTION IN ANY WAY. RIFLE OPERATES PROPERLY
IN ALL RESPECTS.
TRIGGER PUL 5 POUNDS; SEAR-LIFT .007"
DATE OF MFG: 01-81

PARTS:	\$	0.00	1	26345 TRIGGER ASSEM RH
	\$	0.00		19900005 TEST
LABOR:	\$	0.00	1.	RETURN RIFLE AS-IS
	\$	0.00	2.	INSTALL NEW TRIG ASSEMBLY AT 1/2 NORMAL COST, AS A
	\$	0.00		GESTURE OF GOOD-WILL, IF THAT WILL BETTER RESTORE
	\$	0.00		CONFIDENCE IN THE RIFLE.
	\$	25.00		TRIGGER ASSEM - 1/2 PRICE
	\$	0.00		39-D/A 111-9450
	\$	0.00		HB/HAR
	\$	0.00	**	RETURNED AS RECEIVED - CUSTOMER'S PROPERTY

REPAIRMAN'S INITS: HB NUM OF WKS: 00 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR

*Customer paid as per invoice dated Jan 93 - per Jim
at POC's - it's not as bad?
Just try & repair it Nc as gesture of good will*