

Return
to →

Kent Berns
Winky Gunshop
RRI Box 175

Churdan IA 50051

(515) 389-3794
Weekends

(515) 296-0388 Work
(515) 232-7170 Work

Dear Sir:

I enclosed my Remington Model 700 BDL
.243 serial # C6527598.

The problem is the trigger. When I
got the gun out this fall, it would fire the
~~after~~ minute the safety was put on Fire.
If I ~~worked~~ worked the bolt with the
safety off, it would fire when the bolt
was closed. I also noticed that the trigger had a lot of travel.

I then took the gun apart and adjusted
the trigger ~~stop~~ stop screw. It was adjusted
according to your instruction manual for the
least amount of trigger overtravel. It took considerable
adjustment.

When I put it back together, the gun would not
fire until the trigger was pulled. But the trigger
tension was only two pounds. I didn't try adjusting
the pull of trigger screw.

Please do whatever it takes to fix the problem.
Luckily nobody got hurt. It is possible that some
rem oil seeped down into the trigger assembly.

My GM MasterCard # 5437 0002 1031 7113
expires 01/96

The Gun was bought new from Bill Hicks
Company (a wholesaler) in January 1991

Instructions enclosed at other
end.

(Fix Trigger)

Kent Berns
Winky Gunshop
RR1 Box 125
Churdan IA 50050

Home Phone (515) 296-0388

Weekend Phone (515) 389-3794

Work Phone (515) 232-7170