

REPAIRING & ESTIMATING REPORT

FIREARM		CUSTOMER ORDER NO.			
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
12/07/90	12/13/90	RX 11-73	6486425	700 7MM MAG BDL	R 90-32518
ACCESSORIES		W/STUDS SCOPE BASE			

FROM:	SHIP TO:
BILLS SPORTING GOODS 1016 S. LYNN RIGGS CLAREMORE OK 74017	BILLS SPORTING GOODS 1016 S. LYNN RIGGS CLAREMORE OK 74017

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *Discharges sometimes when safety is taken off*

MAIN FAULT *Tugger has been improperly adjusted outside factory - adjust trigger from Tugger full and confirmed adjustment. Tugger full movement at 1/2 pounds pull (no trigger, 1/2 traction), examine & return*

PARTS *Offer to properly re-adjust present trigger assembly as we can install a new trigger assembly at 1/2 normal cost, and get you of good-will.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE