

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 91-23633

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/14/91

11/20/91

WD 8-77

6577001

700 30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

BIG BEAR SUPPLY  
4800 S 10TH ST  
GREAT FALLS

MT 59405

BIG BEAR SUPPLY  
4800 S 10TH ST  
GREAT FALLSMT  
59405

CUST NO:003285 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

"MR WEBSTER SAID THAT WHEN HE WAS MOVING THE SAFE TO  
fire, the gun discharged".

MAIN FAULT

Cannot duplicate complaint, however, trigger assembly has been inspected  
adjusted outside factory - 1) trigger pull measured at 1 1/2 pounds 2) over travel  
excessive - foreign red color sealant on thru two (2) adjusting screws. Trigger  
pull adjustment screw has been backed-out to the point there is no resistance  
spring force on trigger, therefore, the rear engagement can vary each time the bolt  
is cocked. Quickly closing the bolt causes the firing pin to follow down.  
Sear lift .007"

PARTS

COMMENTS

Offer new trigger assembly at 1/2 round  
cost, as a gesture of customer good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS01105