

Remington

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00064112	Description/Serial Number E6514920 REPLACEMENT F6238013Z	Repairman - Chuck Dekanek
Account # - R-	Model 700 Center Fire Caliber: 22250	Date Received - 4/10/2003
	BDL	Estimate Date -
		Current Date - 4/24/2003
Customer SHAWN BLALOCK 2418 EAST TREATY LINE RD PORTLAND, IN 47371 US		Return To SHAWN BLALOCK 2418 EAST TREATY LINE RD PORTLAND, IN 47371 US
Phone (H) (260)-726-4280		Fax
Phone (W) (260)-726-6689		Email

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE			M123	FORWARD TO PRODUCT SERVICE F
	FOR INSPECTION				
M990	FIRED ON SAFE				

Material #		MaterialDesc		Repair		Quantity	Quantity	Quantity	Warranty
						Needed	From Inv	From Kit	(Y/N)
Service									
4000104		ARMS SERV SHIPPING & HANDLING				0	0	0	Y
4000254		GR-FIREARM REPLACEMENT				1	1	0	Y
Service Total:						1	1	0	

Problem/Notes	Exchange for new M/700 BDL 22/250 RAMAC 5783 per FLS.4/10/03				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date