

Repair Order Number



Repair Order Number RE00064198	Description/Serial Number B6500060	Repairman - Richard Hiltz Date Received - 4/8/2003
Account # - R-	Model 700 Center Fire Caliber: 300 BDL MAG	Estimate Date - Current Date - 4/16/2003
Customer LARRY BERNOR 214 E LYNN TULARE. CA 93274 US		Return To LARRY BERNOR 214 E LYNN TULARE. CA 93274 US
Phone (H) (559)-686-5355 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M992	FIRES WITH SAFETY ON	M992	FIRES WITH SAFETY ON

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	N
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		1	1	0	

ProblemNotes	rifle will fire sometime when i take off of safty trigger assembly compornents seized up dirty replace trigger at 1/2 msp go ahead				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date