



Repair Order Number

Repair Order Number RE00051391	Description/Serial Number 6481776	Repairman - Robert Frink Date Received - 9/3/2002
Account # - R-	Model 700 Center Fire Caliber: 270 BDL	Estimate Date - Current Date - 9/10/2002
Customer CARROLLS GUN SHOP INC 1612 NORTH ALABAMA RD WHARTON, TX 77488 US	Return To CARROLLS GUN SHOP INC 1612 NORTH ALABAMA RD WHARTON, TX 77488 US	
Phone (H) (979)-532-3175 Phone (W)	Fax (979)-532-2810 Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M238	CLEAN & INSPECT	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	Action and trigger assembly dirty. White powder substance on action. Poor maintenance. Replace trigger assembly \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357


10 LBS 1 OF 1

COD

SHIP

TO:

CARROLLS GUN SHOP INC
1612 NORTH ALABAMA RD
WHARTON TX 77488




TX 774 9-12



UPS GROUND

TRACKING #: 1Z 114 813 72 1194 0214



BILLING: P/P
COD \$20.00

INV#: RE00051391

ASC 05.00 J65X/J64X 16.DA 01/2002