

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number

RE00048182

Account # - R-

Description/Serial Number

285174

Model 700 Center Fire Caliber: 308 BDL

Date Received - 7/3/2002

Estimate Date - 6/25/2002

Current Date - 7/15/2002

Customer

BRADY CROMER
2622 PARK ROAD

EAU CLAIRE, MI 49111 US

Return To

BRADY CROMER
2622 PARK ROAD

EAU CLAIRE, MI 49111 US

Phone (H) (616)-944-5716

Phone (W)

Fax

Email brady@OTM.Net

Problems

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M238 CLEAN & INSPECT

Found

M238 CLEAN & INSPECT
M239 REPLACE TRIGGER ASSEMBLY

Technician's Comments

Condition REC'D W/ MARRED WOOD.

ProblemNotes Trigger adjusting and stop screws re-set. Replace trigger assm. at spec. price.

Parts and Labor

Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000117	GR-PROOF	1	Y
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		24	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

BRADY CROMER
2622 PARK ROAD
EAU CLAIRE MI 49111




MI 490 2-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 9101



BILLING: P/P

INV#: RE00048182

ASC 05.00 J69X/J64X 16.0A 01/2002