

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL JJM	CUSTOMER ORDER NO.			
DATE RECEIVED 12/26/90	DATE OPENED 01/03/91	DATE CODE	SERIAL NUMBER A445396	MODEL AND GRADE 700 270 BDL
ACCESSORIES			ORDER R 91-00186	

L/STUDS

CO 4-77 2ND TIME IN

FROM:

CONTI, CARMINE P
89 RICCIARDONE AVE
TORRINGTON

CT 06790

SHIP TO:

CONTI, CARMINE P
89 RICCIARDONE AVE
TORRINGTON

CT
06790

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						V412095790

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☒ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"Fires when safety moved forward"

MAIN FAULT *Tugger assembly is rusted - tugger and connector not moving freely on front gun. Disassembly of barrel - action from stock revealed cupda side of barrel and receiver have rusted areas. It appears that the rifle became wet in use and was not disassembled for proper cleaning and maintenance.*

Replace tugger assembly at m- shop, as a gesture of good-will.

When rifle is returned, please include a copy of the new M/700 owner manual which outlines proper lubrication and maintenance procedures.

REPAIRMAN [Signature]	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PS01614