

CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-12836

CUSTOMER ORDER NO.

RECEIVED 28/93 DATE OPENED 06/02/93 DATE CODE B1-1-74 SERIAL NUMBER A62528-4 NEW SERIAL NUMBER MODEL AND GRADE 700 22-250 BDL/VAR
SERIES W7ST00S SCOPE BASE

SHIP TO:

DALES GUNS
9861 DYER ST 7
EL PASO

TX 79924

DALES GUNS
9861 DYER ST 7
EL PASO

TX
79924

CUST NO: 029576 C.O.D.L

INVENTORY NUMBER ACCOUNT NUMBER N/C FROM DATE ESTIMATED VIA UPS

CONDITION
W
SLIGHTLY WORN
DRN
SLIGHTLY WORN
UNREPAIRABLE
REPAIRED

REPAIR CHARGE 25.00
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	refle	B1	discharges when the safety is disengaged		
GENER GROUP		B2			E1	F1
ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

AULT Upon receipt trigger bar, would not retract. Examination revealed
very sticky, gummy substance on action, bolt stop, return, and
the housing. Trigger adjustment screws appear to have been tampered with
and is sealed. Trigger pull below minimum spec. Left May 1976
Trigger pull - less 2 lbs
in left - .010

COMMENTS

Replace complete trigger assembly
at 1/2 normal replacement cost, in
gesture of good will. Clean action
Go ahead per phone 7/16/93 Mr. Benal

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
83					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS01649