

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00048378 Account # - R-	Description/Serial Number A6412952 Model 700 Center Fire Caliber: 3006 ADL	Date Received - 6/24/2002 Estimate Date - Current Date - 6/28/2002
Customer JOHN DILL 301 DOMINIC DR SCOTT DEPOT. WV 25560 US Phone (H) (304)-586-0616 Phone (W)	Return To JOHN DILL 301 DOMINIC DR SCOTT DEPOT. WV 25560 US Fax (304)-586-0620 Email MULITICOATJOHN@AOL.COM	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M238	CLEAN & INSPECT
M238	CLEAN & INSPECT	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
Condition	REC'D W/ BKN FRT SGT.
Problem/Notes	Action and trigger assm. dirty. All 3 trigger adjusting screws re-set. Replace trigger assm.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000116	GR-LABOR	20	N
4000117	GR-PROOF	1	Y
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		24	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

JOHN DILL
301 DOMINIC DR
SCOTT DEPOT WV 25560




WV 257 0-10



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 5598



BILLING: P/P

INV#: RE00048378

ASC 05.00 J69K/J64K 16.0A 01/2002