

James Ferlin Dalton  
1952 Hunters Ridge Rd.  
Hillsville, VA. 24343

Dec. 2, 2002

ATTN: Remington Arms, Customer Service

RE: Remington 700-280 Caliber

About 2 Years Ago This Rifle was sent back to Remington For Repair. You Then sent it to Keidel's Gunsmithing, SVC, in Washington, PA. The Problem With This Rifle is that The Safety And Trigger Assembly Do Not Work Properley.

When You Put The Safety On, Chamber A Shell, Close The Bolt, And Push Safety Off, The Rifle Will Fire On It's Own, Without Touching The Trigger.

It Does Not Do It Every Time. Sometimes You Can Chamber A Shell 3 To 10 Times, Before it will fire On it's Own, Without Touching The Trigger.

Please Check The Bolt, Safety, Trigger Assembly, And Anything Else That Might Cause The Rifle To Go Off, When The Safety Is Pushed In Fire Position, Without Touching The Trigger.

This, (Enclosed), is the Bill that I Paid when the Gun was Repaired Before. I Feel A New Trigger Assembly Should Last More Then 2 Years. Please Fix It Properly This Time. Thank-You.

Sincerly,

James Ferlin Dalton  
Dec. 2, 2002

*T/A adjusted to unsafe  
condition replace y note  
customer 1/2 price JB 12/18/02*

*PS you may have to Jar the Rifle  
to get it to go off.*

*57280*