

14 Fellview Drive  
Pittsford, NY 14534  
May 4, 1994

Service Dept.  
Remington Arms  
1007 Market Street  
Wilmington, DE 19898

Dear Sirs,

Re: Remington Model 600 .243 Rifle S/N 91041

Several years ago, I inherited this rifle from my father. Since then it has been stored away in a closet and has not been fired. As a point of further identification, it has "Illion, NY" stamped on the barrel.

Recently I saw a feature on TV showing various guns with unsafe features or mechanisms. That show demonstrated a Remington Model 600 which would often fire when the safety was released. That prompted me to experiment with the safety on my rifle.

My safety appears to work normally UNLESS you press the trigger while the safety is engaged. The firing pin won't drop while the safety remains engaged but immediately drops upon the RELEASE of the safety. This occurs 100% of the time which, of course, renders the rifle totally unsafe since the bolt cannot be operated without releasing the safety.

Would you please advise concerning what must be done to correct this situation and also how I should go about getting it done.

Yours truly,

Earl Dillman  
(716) 586-6387