

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL JJM	CUSTOMER ORDER NO. 12898					R 94-35173	
DATE RECEIVED 12/02/94	DATE OPENED 12/07/94	DATE CODE EB 10-81	SERIAL NUMBER B6325562	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	ADL	
ACCESSORIES W/STUDS		L/SIGHTS					
FROM: D & G SPORTS & WESTERN 215 4TH ST S GLASGOW MT 59230				SHIP TO: D & G SPORTS & WESTERN 215 4TH ST S GLASGOW MT 59230			
CUST NO: 003260 ILIONL							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED 12-29-94	VIA UPS
GUN CONDITION				REPAIR CHARGE 20.00			
<input type="checkbox"/> NEW <input checked="" type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED				EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 28.00			
CUSTOMER CONCERN		AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE			B1				
TRIGGER GROUP			B2				F1
BOLT ASSY.			B3				F2
BARREL ASSY.			B4				F3
REC. ASSY.			B5				F4
WOOD				C1	D3	E5	F5
METAL				C2			
MAIN FAULT: Life 1981							
<p>We could not duplicate the customer reported problem, however, inspection revealed that the trigger adjustment was not set. The trigger pull measured about 10.5 lbs. The action and trigger spring are correct with a gummy resistance causing the bolt stop release to work sluggish. The gun is also dirty.</p> <p># 816345</p> <p>Expensive the trigger adjustment is done the action is 1/2 the normal speed test, as a gesture of good will.</p>							
PARTS		COMMENTS					
		REPAIRMAN PROOF CLEAN TEST TARGET PATTERN					
		GALLERY TESTER DATE DATE DATE DATE DATE					
<p>Go ahead</p> <p>OFFICE COPY</p> <p>RD6925 REV. 1/94</p>							