

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 09/26/90	DATE OPENED 10/05/90	DATE CODE AA 2-00	SERIAL NUMBER A3200135	MODEL AND GRADE 700 30-06 BDL		ORDER R 90-25820	
ACCESSORIES SLING STRAP W/STUDS		W/SWIVELS		SCOPE BASE			
L/REAR SIGHT							

FROM:	SHIP TO:
DENNIS COMPANY 115 S 4TH ST ELMA WA 98541	DENNIS COMPANY 115 S 4TH ST ELMA WA 98541

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM DATE	ESTIMATED 10-12-90	VIA UPS
----------------	--------------------	--------------------------------	-----------	------------------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☒ MISUSED	☐ MARRED
CUSTOMER'S REQUEST	<i>Gun goes off by itself</i>				

MAIN FAULT	<i>Trigger assembly contaminated with sticky-gummy residue. Internal parts of trigger assembly not moving freely - rear safety cam is stuck to back plate of trigger assembly - as result, BB cannot be inserted into action because of stuck rear safety cam. Rifle has not been properly maintained.</i>
PARTS	

<i>Send repair quotation for new trigger assembly at the normal price - the present assembly cannot be properly cleaned</i>					
REPAIRMAN W/B	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV 6/88