

DAN EVERETT  
3541 GRIER NURSERY RD  
STREET, MD. 21154

LR= 2/97  
HAMMER CRACKED through at  
pin hole - bent out of  
position. Firearm rusty -  
Replace TA clean rifle  
MK - charge 230145

Daytime phone 410-879-9930

FLS 11/4/02

Problem - Gun discharges when safety is  
operated.

I would like to know what the problem  
is with the gun and what was done to  
correct the problem.

Thank you  
Dan Everett

ML203162

Model: 700ML



RE00054988