

Date: 8/24/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: EAA

R.E. Number: 100053

Reason for inspection: FBC

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: C6335479 Date of Manufacture: 2/89

Overall external condition: DIRTY

Barrel condition: SS bbl. w/ BORE

Receiver condition: CARBON STL. REC.

Stock condition: SYN.

Bolt/firing pin condition: DIRTY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: DIRTY

Headspace: -

Function evaluation:

Feeding: Mag. Fall + spa. miss

Extraction/ejection: —

Trigger pull: 3 1/4#

Manual safety: O/CAY

Test firing results (if applicable): —

DISPOSITION

TRIG: Adj. screws ALTERED, TRIG-ASSM. DIRTY. Replace w/ new
TPA AT 1/2 msp. check over completely. Set TRIG pull at
min Specs.

ADDITIONAL COMMENTS