

X

**Terry W. Eatherton**

2019 Cheshire Lane  
Houston, Texas 77018

RECEIVED

APR 5 1994

APR 13

CONSUMER SERVICE

Remington Arms Company  
1007-T Market St.  
Wilmington, DE 19898

Attn: Customer Service


To Whom It May Concern,

I saw the segment on 60 Minutes (20 March 94) concerning gun manufacturing and there was a statement from a lawyer on Remington bolt action rifles. This lawyer alleges that Remington bolt action rifles (per 1974) have a malfunctioning safety.

I have a Model 700 ABL in .243 (Serial No. 6603280) manufactured prior to 1974. I wish to go on record stating that on 25 Nov 90 I had the same experience of the rifle discharging when the safety was released. As you know, the rifle can not be unloaded unless it is taken off safety. The gun was being unloaded and as soon as the safety was released the rifle discharged shooting a hole my 1988 Suburban tail light. The rifle has not been used since.

I wish to know how this defect can be corrected and what you intend to do about correcting it.

Regards,



Terry W. Eatherton