

REPORT

NEW SERIAL NUMBER

700

ANTHONY FAZIO

58-08 188th

FLUSHING N.Y. 11365

Anthony Fazio
58-08 188 th Street
Flushing, NY 11365
April 15, 1995

GUN: MODEL 700/BDL
30-06

Problem: GUN Discharges on its own
(SAFETY or TRIGGER)?

I am returning my 30-06 Model 700/BDL to be thoroughly checked out by our repair department.

During a recent hunting trip I experienced a frightening discovery about this gun. The morning of the hunt I was loading the rifle as usual with the safety on and gun pointing in a safe direction. After chambering the last round I engaged the bolt and took the safety off. It was at this time that the gun discharged on its own. Being extremely startled by this, I immediately unloaded the gun and brought it back to camp.

Unfortunately I have been able to duplicate this trouble a number of different times and ways. As mentioned above, with the safety on and bolt engaged, taking the safety off will cause a discharge. Also on occasion with the safety off, simply engaging the bolt will cause the same, a discharge. As a long time owner of Remington Firearms this is the first incident that I can recall where there has been any defect in craftsmanship.

Please notify me of the findings and actions that that will be taken to rectify this problem.

Sincerely,

Anthony Fazio

Anthony Fazio

Days: (212) 647-2207
Eves: (718) 357-8017

58-08 188th
FLUSHING, NY 11365

ATTENTION

REPAIRMAN <i>REP</i>	PROOF	CLEAN ✓	TEST ✓	DATE	DATE	DATE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925