

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 12/07/90	DATE OPENED 12/13/90	DATE CODE EF 10-85	SERIAL NUMBER B6752073	MODEL AND GRADE 700 30-06 MTN		ORDER R 90-32503
ACCESSORIES W/STUDS						

FROM:

FLEURY'S SPORTING GOODS
RT 202 BOX 331
WINTHROP ME 04364

SHIP TO:

FLEURY'S SPORTING GOODS
RT 202 BOX 331
WINTHROP ME
04364

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/> CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	------------

--	--	--	--	--	--

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Customer took safety off, gun would not fire, put safety on & off a few times, then gun discharged without pulling trigger"

MAIN FAULT

Could not duplicate complaint, however, trigger assembly has been improperly adjusted outside factory. Sealant missing from all adjustment screws. Trigger pull medium to heavy, insufficient over-travel, excessive rear engagement. Trigger has been broken off safety detent spring.

PARTS

Send repair quotation for new trigger assembly at 1/2 normal price, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PS02422