

Repair Order Number



Repair Order Number RE00062249	Description/Serial Number 6637675	Repairman - Dale Lewis Date Received - 3/18/2003
Account # - R-	Model 700 Center Fire Caliber: 270 BDL	Estimate Date - 3/6/2003 Current Date - 3/25/2003
Customer STAN FIELDS 156 SEITZ DRIVE SALINA, KS 67401 US	Return To STAN FIELDS 156 SEITZ DRIVE SALINA, KS 67401 US	
Phone (H) (785)-827-1186 XH Phone (W) (785)-493-4693 Xcell	Fax Email	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M994	BOLT LOCK/FIRED ON SAFETY		

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000119		GR-TEST		1	1	0	Y
4000294		GR-CHECK TPA		1	1	0	Y
Service Total:				22	22	0	

Condition	*				
Problem/Notes	mfg 5/73...qoute \$20 for new ta and cleaning actionunder bolt lock mod program.sear sticks to sidewalls of trigger housing due to improper cleaning per product service				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date