

6186

From:



Mike Fairman
3547 Orchard Heights Rd. NW
Salem, OR 97304-1642

PH# 503-364-6186

MODEL 7 LS / 7mm RUM / SER# 7775242

503-364-6186
My Rifle was purchased 6 mos. ago.
IT Has 100 RDS. Fired Through it.

ME
THE RIFLE functioned flawlessly until 10/21/04 (The first day of a long planned Hunting Trip). The problem occurred while checking zero (actually I was showing off by repeatedly hitting a 12" diameter Rock at 500 yards from the kneeling position). On the third shot the rifle failed to cock. ~~I then~~

missed
I opened the bolt and flicked on the safety. I then chambered a cartridge, got back in position, sighted on the offending rock, yelled "Fire in the Hole". With my finger along side the trigger guard I released

the safety and the rifle fired. ~~After~~

AFTER inspecting the rifle, I determined that the trigger was NOT returning forward by itself and the only thing keeping the sear from releasing (unless the trigger was pushed forward) was the safety.

IT'S THE MIDDLE OF DEER, ELK, AND BEAR SEASON HERE! I NEED MY RIFLE.
(I ACTUALLY HAVE A BACK UP OF COURSE) BUT THIS MODEL 7 IS MY BABY; IT'S THE FIRST NEW RIFLE I'VE BOUGHT IN TEN YEARS AND IT'S A ~~REALLY~~ SHOOTER.

THE ONLY MODIFICATIONS TO THE RIFLE ARE THE ADDITION OF ~~THE~~ TALLEY QR MOUNTS, A 2X7 LEUPOLD VX-II, AND A RECOIL PAD ALL DONE BY ME. (DON'T LAUGH TO HARD AT MY RECOIL PAD FITTING.)

ALSO WHEN I PICKED UP THE RIFLE FROM THE GUNSHOP (AFTER WAITING A WEEK FOR THE SPECIAL ORDER TO COME IN) THE TRIGGER PULL MEASURED 8 LBS AND THE GUNSMITH LOWERED IT TO ~~7~~ 5 LBS.

I DON'T WANT ANYTHING, BUT MY RIFLE BACK AS FAST AS HUMANLY POSSIBLE

P.S. THANK GOD I'M ONE OF THE FEW PEOPLE THAT TAKE FIREARMS SAFETY SERIOUSLY AS THEY SHOULD (DEADLY SERIOUSLY)

RESPECTFULLY: MIKE FAIRMAN