

Safety problem

6#

1/67

Sent Gun in for safety bolt/lock recall in December of 2003.

After receiving rifle back I remounted scope and fired approx. 1 box of shells through it to resight scope.

Used gun during the October moose season and took a nice cow with one shot.

Did not clean gun before November deer season as this was only weeks away.

Opening day of deer season temperature was about 25 degrees I shot at a buck at 8: am and missed with the first shot. Cycled another shell into the gun and when I tried to shoot again nothing happened. Emptied this shell and remainder in magazine onto the ground with none of the shells firing. I looked the gun over and realized the trigger was still in the all the way back position. I fiddled with the safety and put another shell in the gun, when I closed the bolt the gun discharged. (safety was in the off position) I again put another shell in this time with the safety in the on position and nothing happened when I closed the bolt this time. During all of this the deer remained in sight and I was able to harvest it with the last bullet I had put in the gun.

Called your support people and they wanted the gun back for another inspection.

Please contact me with your findings

could not duplicate concern
Trip. Assm rusty. Replace TPA
& clean action at N/C to
restore confidence.
* #230145

Jim Farrell

1084 Barber Pond Road

Pownal Vt. 05261

Home Phone 802 823 5495

Work Phone 413 637 3887

e-mailto: jim.farrell@vt.gov

December 29, 2004

Serial
Number:

80861

Model: 600



RE00090484

1008
4015