

File Number:	21465		Arms Service number:	99632	
Last Name:	FRYER		First Name:	PAUL TODD	
Street:	25 BARKWOOD LANE		City:	CLIFTON PARK	
State:	NY	Zip:	12065	Home Ph:	518-727-4795
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	NEW TA N/C		Settlement Amount:	\$65.00	
Date Opened Rem:	8/9/2005	Date Opened by P/S:	8/9/2005	Caliber:	308
Date of Incident:	8/6/2005	Date Closed:	8/9/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	E6727716	Date Code:	
RAMAC:	700	Date Mfgd:	3/2/2001	Litigation:	☐
Custody:		PreLitigation:	☐	Obsolete:	☐
Time of Modification:	8:38:06 AM				
Date of Modification:	8/24/2005				
Comments: Trigger adjustment screw positions altered, rust visible on bolt release and trigger pin. Trigger not returning under sear. Clean action and install new TA at n/c - charge 230145.					