

*Fla. set up file*

ALBERT B. FAY  
515 HOUSTON AVENUE  
HOUSTON, TEXAS 77007  
713-227-5251

RECEIVED

October 10, 1990

OCT 15 1990

J.A. STEKL

Remington Arms Company  
Arms Services Division  
14 Hoefer Avenue  
Iliion, New York 13357

Attn: Mr. Jim Spekl

Dear Mr. Spekl:

Enclosed is my Remington Rifle which malfunctioned on an Elk Hunt on the Apache Reservation in Arizona on Friday, October 5th. The hunt began on October 1st and I hunted twice a day while in the company of my friend, Mr. Don Ross and a guide who was provided for me. Prior to going on the hunt I had targeted in my rifle, shooting it fifteen times, and after arriving at the camp, I checked the rifle and found that the point of impact had not been changed by shipment. During the course of the hunt we carried the rifle with us in a pickup truck with the chamber of the rifle unloaded, but with the magazine loaded and we were continually loading and unloading throughout the day as we got in and out of the truck.

On the morning of October 5th, my guide had bugled up an Elk to within forty yards, hidden in brush but with a clearing on either side. I fired my first shot, badly wounding the Elk and as I slammed the bolt home for the second shot, the rifle fired as soon as the bolt closed. Once again I tried closing the bolt and once again the rifle fired, at which point the Elk ran away.

After experimenting with the gun we discovered that by pushing the safety forward we were able to make the rifle fire. I am suffering from a heart condition and so was unable to pursue the Elk in order to make the final shot. My friend took the rifle, followed the Elk and eventually shot the final coup de grace.

In view of the fact that this hunt cost me in excess of \$10,000, I am extremely disappointed that I was unable to reduce the Elk to my possession and I feel that the malfunctioning of my rifle was directly responsible. In retrospect I am convinced that I experienced the same malfunctioning of my rifle during another failed Elk hunt four years ago at Vermejo Park in Northern New Mexico.


In consideration of the extremely hazardous conditions which I was exposed to due to this malfunction, I can only say that It is very fortunate that both my friend and I are experienced hunters, having hunted all over the world for many, many years. At no time have I or my gunsmith been alerted to this problem potentially occurring in the BDL 700 actions and I feel that because of the neglect of your company I am due the reimbursement of the costs of my failed hunting trip.

Sincerely,

Ambassador Albert B. Fay

ABF/jh  
enclosure

ALBERT B. FAY  
515 HOUSTON AVENUE  
HOUSTON, TEXAS 77007



Mr. Jim Spekl  
Remington Arms Co.  
Arms Services Division  
14 Hoefler Ave.  
Ilion, New York 13357

