

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS ATTN: J STEKL			
DATE RECEIVED 08/10/90	DATE OPENED 08/10/90	DATE CODE 08 9-70	SERIAL NUMBER A6402657	MODEL AND GRADE 700 270 BDL		ORDER R 90-21743	
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS			

FROM:

**FARRINGTON, ROBERT
3626 LAKE PONTCHORTRAIN
ARLINGTON TX 76016**

SHIP TO:

**FARRINGTON, ROBERT
3626 LAKE PONTCHORTRAIN
ARLINGTON TX
76016**

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------

REPAIR CHARGE						TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	--	--	--	--	--	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"The gun discharged when the safety was released"

MAIN FAULT

Could not duplicate complaint, however, trigger pull below our min. spec. at 2 3/4 # and over-travel out of spec also (excessive) Sear lift .0105". Bolt stop has accumulation of dried oil and stuts sometimes.

PARTS

Offer to either re-adjust present Trigger assembly back into specification, or, if it will better restore confidence in rifle, we can install a new trigger assembly, at no-charge, as a gesture of good-will.

Either option is subject to handling plus return shipping charges/22/90 JLS.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/8

PS02532