

NO phone
Richard Fenner
120 East Madison Avenue
Norfolk, NE 68701

4 April 1994

Arms Service Division
Remington Arms Company, Inc..
Ilion, New York 13357

Ladies and Gentlemen:

After viewing a CBS 60 Minutes segment concerning no federal regulation on the manufacture of firearms. It has come to my attention that some of Remington's Model 700 bolt action rifles may exhibit unfavorable behavior.

I possess a 25-06 Remington model 700 BDL bolt action rifle serial number 6777547 which exhibits such unfavorable behavior concerning the bolt assembly. The firing pin will not remain locked back in the bolt when bolt assembly is actuated to cock and load a new round into chamber. The firing pin may fly forward and discharge the rifle without warning, when the safety is in the fire position. As you already know, the safety will not lock into the safe position unless the firing pin is in the cocked position.

Please recommend a course of action to remedy this situation. Until the problem is repaired, the rifle is useless to me and dangerous.

Sincerely;

Richard Fenner