

Serial
Number:

E6717397

Model: 700



RE00047183

5/24/02

Refill fluid on self release

Autumn (barel bracket) & trigger assembly
Components rusty - appears self was exposed
to excessive moisture & not properly cleaned

Replace trigger assembly & clean autumn at no charge
as part of product - normally this condition
would warrant a repair charge

Charge 230145