

File Number:	20705	Arms Service number:	88577
Last Name:	GILDERDALE	First Name:	BYRON
Street:	315 NORFOLK RD	City:	EAST CANAAN
State:	CT	Zip:	06024
Work Ph:		Home Ph:	860-824-9962
Type Concern:	S	Product Type:	F A T O
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SUPRY	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPLACE TRIGGER ASSEM AT N/C RIFLE NEV		
Date Opened Rem:	12/1/2004	Date Opened by P/S:	12/1/2004
Date of Incident:		Date Closed:	12/2/2004
Date to Analysis:		Date from Analysis:	
Model:	600	Serial:	74904
RAMAC:	600	Manufacturer:	REM
Custody:		Date Mfgd:	8/1/1966
Time of Modification:	9:35:42 AM	Litigation:	
Date of Modification:	12/2/2004	PreLitigation:	<input checked="" type="checkbox"/>
Comments: Trigger assem is contaminated with sticky dried residue causing sear safety cam the stick to the sides of the trigger housing. Rifle never updated. Repair and shipping document 12-10-04.			