

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 5, 1990

Geiser Guns Attn: P.C. Geiser 170 Lenker Ave. Sunbury, PA 17801

Dear Mr. Geiser:

Examination has been completed on the Model 700 BDL 25-06 Rem. caliber rifle, serial number 6851215, that you returned to us a short time ago because, "...the gun would fire when the safety goes off."

The returned firearm, which was produced in April of 1975, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition appeared to be very good for a rifle of this age. In going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal. Trigger pull was measured to be 4 pounds and the sear-lift with the safety in the "on-safe" position was also within specifications at .008".

Examination of the rifle and trigger assembly could not duplicate the malfunction our customer reported. Many attempts were made to cause the rifle to fire when the safety was moved from the "safe" to the "fire" position, but it did not occur. The only way the rifle could be made to fire was with the safety in the "fire" position and the trigger pulled; it functioned properly and as designed.

Since we found the firearm to function normally in every respect, we are prepared to return it in its present condition. However, if our customer desires, we will replace the trigger assembly at nocharge as a good-will gesture, if it will better restore confidence in the rifle (either option is subject to a \$10.00 handling plus the return shipping amount). We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

U.A. Stekl, Specialist

Product Service

JAS: tpp