

RECEIVING AND ESTIMATING REPORT

COMMENTS

#30. Ryle

INITIALS: RLP		CUSTOMER ORDER NO. 722-3741					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
09/14/90	09/26/90	RI 11-88	C6323698	78 30-06 SPT.		R 90-24891	
ACCESSORIES							

FROM:	SHIP TO:
GASSER TRUE VALUE HDWE HWY 61 N P O BOX 424 LANCASTER WI 53813	GASSER TRUE VALUE HDWE HWY 61 N P O BOX 424 LANCASTER WI 53813

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *"... firing at will"*

MAIN FAULT *Trigger assembly rusted from saturation cause internal trigger parts not working, trigger assembly not operating properly.*

PARTS	<i>Replace trigger assembly at no charge.</i>					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

RD6925 REV. 6/88