

TO Whom it may Concern

Purchased This Rifle in
March 1994 From Bill
Hicks + Co.

Has never been Fired
Bolt make a squeaking
noise. Accidentally Dry Fired
Twice during operation
of Bolt. Please Repair
and Return to

Gibbs Gun Shop

RR 2 Box 234

Metter, GA 30439