

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-32688

INITIAL JJM	CUSTOMER ORDER NO. 54735				
DATE RECEIVED 11/11/94	DATE OPENED 11/14/94	DATE CODE LB 2-81	SERIAL NUMBER B6303354	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 BDL
ACCESSORIES HARD CASE		W/STUDS			

FROM:

GANDER MOUNTAIN INC.
614 - 2ND ST SOUTH
WAITE PARK

MN 56387

SHIP TO:

GANDER MOUNTAIN INC.
614 - 2ND ST SOUTH
WAITE PARKMN
56387

CUST NO: 097547 C.O.D.L

ACCOUNT NUMBER 063103	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED			REPAIR CHARGE 210.00 EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 28.00		

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

After May 1981, we could not duplicate the reported concern. However, examination revealed that the bolt stop was not working properly. The trigger action and trigger assembly are covered under a 3-year warranty. No warranty, but and not this rifle has been poorly maintained.

26345

COMMENTS

Repair the trigger assembly & clean the action at 1/2 the normal repair cost, as a gesture of good will.

Go ahead

REPAIRMAN CC	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8925 REV. 1/94

PS02921