

11-28-94

Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, N.Y. 13357

Subject: Model 700 Remington 30-06 SERIAL # 6797854

This gun is very dangerous, it is subject to misfire when loading. This gun has misfired on two different occasions. The first time I was fixing to shoot a buck, I pushed the safety off to fire and pulled the trigger and the gun would not fire. I then ejected the bullet and reloaded, when I closed the bolt the gun fired. I did not have my finger on the trigger when this happened.

The second time the gun misfired, I was standing next to my vehicle loading the gun, when I closed the bolt the gun fired. This happened on November 19, 1994. The shot hit my 1989 Ford Bronco and did several hundred dollars damage. I unloaded the gun and worked the bolt five times and each time the gun fired (dry fired).

I have noticed that when you pull the trigger and close the bolt to store the gun during the off season, so that no tension would be on the firing pin, and when you reopen the bolt it hangs up.

I have lost all confidence with this gun. Due to the danger of the gun misfiring I cannot consciously sell or trade the gun. I am requesting that Remington fix this gun and assure me that the gun will not misfire when being loaded.

If you need further information please call me at (615) 354-2088 after 6:00 p.m. central time.

Thank you,

Tom Ed Hickey

RT 4 Box 335 A

Rockwood TN 37854

DATE

PATTERN

PS03058