

Repair Order Number



<b>Repair Order Number</b> RE00077654	<b>Description/Serial Number</b> 6893716	<b>Repairman -</b> Richard Hilts <b>Date Received -</b> 2/27/2004
<b>Account # - R-</b>	<b>Model 700 Center Fire Caliber:</b> 270 ADL	<b>Estimate Date -</b> <b>Current Date -</b> 3/4/2004
<b>Customer</b> ROBERT HAYDEN 578 WHITE OAK GROVE RD RINER, VA 24149 US		<b>Return To</b> ROBERT HAYDEN 578 WHITE OAK GROVE RD RINER, VA 24149 US
<b>Phone (H)</b> (540)-763-2400 <b>Phone (W)</b>	<b>Fax</b> <b>Email</b>	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M992	FIRED WHEN BOLT WAS CLOSED / 3 X	M992	FIRED WHEN BOLT WAS CLOSED / 3

<u>Material #</u>		<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
<b>Part</b>						
F26345		700 TRIG ASSB RH	1	1	0	Y
<b>Part Total:</b>			1	1	0	
<b>Service</b>						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116		GR-LABOR	20	20	0	N
4000118		GR-CLEAN	1	1	0	Y
4000119		GR-TEST	1	1	0	Y
<b>Service Total:</b>			22	22	0	

<b>Condition</b>	CHIP IN GRIP AREA				
<b>Problem/Notes</b>	could not duplicate action & trigger assembly covered with sticky substance & rust poor mainting replace trigger \$20.00 GO HEAD				
<b>Repairman</b>	<b>Proof</b>	<b>Clean</b>	<b>Test</b>	<b>Target</b>	<b>Pattern</b>
<b>Gallery Tester</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>	<b>Date</b>